



VLB100 Instructions

Visit www.victorylighting.co.uk for more information

UV Inks:

1. Wipe Anilox & Metering rolls down to remove excess ink before cleaning.
2. Apply **VLB100** to a heavy-duty paper towel and wipe over surface until clean.
3. Dry with a clean rag or heavy-duty paper towel.

Use **VLB100** full strength or dilute up to 30% with water.

Water Base:

Use **VLB100** full strength or dilute as needed

VLB100 can be used on plates, ultra-sonic cleaners, floor scrubbers, and entire press area as an ink cleaner and floor scrubber.

- DO NOT soak aluminum parts
- Wear gloves. **VLB100** is a safe product but will dry out skin

